### Water Quality Monitoring in Georgia

Thematic workshop on the implementation of the water component of the ENI SEIS II East project in Georgia

6 November, 2017

Tbilisi, Georgia






#### National Environmental Agency

# Department of Environmental Pollution Monitoring

- Identification of different levels of pollution caused by anthropogenic factors, regular monitoring of background pollution, atmospheric air pollution, surface water pollution, atmospheric precipitation's pollution, chemical pollution of the soil and radiation pollution through observation points and field expeditions;
- ➤ Preparation of the information, concerning environment pollution conditions;
- Participation in the activities, concerning identification of extremely high environment pollution (including pollution caused by accidents);
- Preparation of yearbooks, bulletins, reviews, notes and other materials consisting of actual information on environment pollution.

## Structure of the Department




## Environmental Pollution Monitoring



#### BRIEF HYSTORY

- **❖**1960s − started routine monitoring of surface water pollution;
- **❖** 1980-1990 the maximum number of monitoring stations (more than 120);
- \* 1990-2004 decline of monitoring activities;
- **❖** 2004 − started upgrade of existing monitoring network, mainly due to foreign assistance programmes

#### Water Quality Monitoring Points



#### Water Pollution Monitoring Network

#### 158 MONITORING POINTS

81 – IN WEST GEORGIA

77 – IN EAST GEORGIA



Sampling





#### QA/QC



Raf. No. 1233/2009/420-113 Registration number: 93.02

C

of performance of laborate

Laboratory: Department of Environment Address: David Agmashenebeli 150, 01 Laboratory code: 13

> took part in the interlaboratory co MPS - ZOV - 9/2009 "

directed towards the determination concentration level of surface/waste wat-The results of the laboratory confirmed i parameter:

This serves as a basis for issui interlaboratory comparison test MPS-ZO

This certificate is valid only in conju

Bratislava, 28th October 2009

Dr. Ladislav Šuster PTS Coordinator

Responsible persons: Dr. Jana Tkáčov Dr. Ladislav Šu

Appendix Results of Laboratory

WRVSNWRL/PTS/Certificate MPS-ZOV-9/2009



ᲡᲡᲘᲞ "ᲐᲙᲠᲔᲓᲘᲢᲐᲪᲘᲘᲡ ᲔᲠᲗᲘᲐᲜᲘ ᲔᲠᲝᲒᲜᲣᲚᲘ ᲝᲠᲒᲐᲜᲝ – ᲐᲙᲠᲔᲓᲘᲢᲐᲪᲘᲘᲡ ᲪᲔᲜᲢᲠᲘ"

#### 3360R063600L 8088083

GAC-TL-0094

ადასტურებს, რომ

სსიპ გარემოს ეროვნული სააგენტოს ატმოსფერული, ჰაერის, წყლისა და ნიადაგის ანალიზის საგამოცდო ლაზორატორია

მდებარე: ქ. თბილისი, დავით აღმაშენებლის გამზ. 150, შეფასდა და აკმაყოფილებს ეროვნული სტანდარტის

#### სსტ ისო/იეკ 17025:2010-ის მოთხოვნებს

კ<mark>რედიტეტულია შემდეგ სფეროში:</mark> 1. სასმული, ჩამდინარე, ზედაპირული, გრუნტის, ტბის, ზღვის წყლებში მძიმე მეტალების ამსაზღერა: (ალუმინი, დარიშნანი, ბარიუმი, კადმიუმი, ქრობი, სპილენში, მანგანუში (ჯაბური), მოლიზდენი (ჯაბური), ნიკელი, ცეია, სულენი, სტრონციუმი, კობალტი და თუთია: 2 წყალბადის მაჩვენებლის-PH განსაზღვრა; . "აკრედიტაციის სფერო", დანართი 1).

აკრედიტაციის ცენტრის გენერალური დირექტორი

რეგისტრაციის თარიღი 23 დეკემზერი 2014 წ.

domodos

23 დეკემბერი 2018 წ.

0186 თბილისი, ალ. ყაზბეგის გამზ. No425



#### FICATE

nterlaboratory comparison tests

Department of Environmental Pollution

isi, GEORGIA

ce Inorganic Analysis"

ameters associated with water quality at the eld on 22nd September 2009.

sfactory performance in the determination of the

r, nickel

firmation of Performance of Laboratory in the on with the appendix attached

> Dr. Jarmila Mekovinská Head of SNWRL



### Assessment and Reporting

nea.gov.ge meteo.gov.ge



საქართველოს გარემოსა და ბუნებრივი რესურსების დაცვის სამინისტრო





გარემოს ეროვნული სააგენტო

საქართველოს ტერიტორიაზე ზედაპირული წყლეზის ხარისხის წელიწდეული

ᲒᲐᲠᲔᲛᲝᲡ ᲔᲠᲝᲕᲜᲣᲚᲘ ᲡᲐᲐᲒᲔᲜᲢᲝᲡ ᲒᲐᲠᲔᲛᲝᲡ ᲓᲐᲑᲘᲜᲫᲣᲠᲔᲑᲘᲡ ᲛᲝᲜᲘᲢᲝᲠᲘᲜᲒᲘᲡ ᲓᲔᲞᲐᲠᲢᲐᲛᲔᲜᲢᲘᲡ ᲛᲝᲜᲐᲪᲔᲛᲔᲑᲘ 2016 ᲬᲔᲚᲘ

*ᲗᲒᲘᲚᲘᲡ*Ი 2017

# THANK YOU FOR ATTENTION!

